ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0365, W0355, WA408, W0359	Chikka Muniswammappa Lyt, 2nd Crs, NA	BAgalagunte
Segment No.	**Total Length (m)**	
14/C-W0365/S015535	69.90	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	69.90	77.503214	13.058027	77.502586	13.058171	6th cross	dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to CC road and drain at 6th cross and other cross roads besides of Sub division office ward No 14 Bagalagunte	2000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		014-18-000035
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/wo/360/17-18	26/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
26/03/2018	25/03/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		1999025.00
Phone No.	**E-Mail ID**	
9448512985		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು